


Mercedes 722.6

sonnax®

TIME TESTED • INDUSTRY TRUSTED®

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

1 68942-10K
**TC Lockup Clutch
Regulator Valve Kit**



Helps cure:

- Converter apply & release complaints
- Converter codes
- Lube failures


Note: Requires tool kit F-68942-TL10 & the VB-FIX reaming fixture.

2 68942-23K
**TCC Damper Valve
& Sleeve Kit**

Helps cure:

- Harsh lockup

3 68942-16
**Oversized Manual
Valve**




Helps cure:

- Reduced line pressure
- Delayed engagements

Note: Requires tool kit F-68942-TL16 & the VB-FIX reaming fixture.

4 68942-07K
**Pressure Regulator
Valve Kit**




Helps cure:

- Loss of 2-3, 4-3 neutral
- Soft shifts under acceleration

Note: Requires tool kit F-68942-TL7 & the VB-FIX reaming fixture.

5 68942-06
**Outer Pressure
Regulator Sleeve**



Repairs outer bore only

Helps cure:

- Loss of 2-3, 4-3 neutral
- Soft shifts under acceleration

Note: Requires tool kit F-68942-TL6 & the VB-FIX reaming fixture.

6 68942-17K
**Oversized Regulating
Valve Pressure Control
Valve Kit**




Early & Late Units

Helps cure:

- Delayed engagements
- Upshift/Downshift flares

Note: Requires tool kit F-68942-TL14 & the VB-FIX reaming fixture.

7 68942-14K
**Lubricating Pressure
Control Valve Kit**




Helps cure:

- Delayed engagement
- Poor performance/higher stall speeds

Note: Requires tool kit F-68942-TL14 & the VB-FIX reaming fixture.

8 68942-19K
**1-2, 4-5 Overlap
Control Valve Kit**




Helps cure:

- Harsh/Flare/Cycling of 1-2/4-5 shifts
- Slipping Gears

Note: Requires tool kit F-68942-TL19 & the VB-FIX reaming fixture.

9 68942-27K
**2-3 Overlap Control
Valve Kit**




Helps cure:

- Harsh/Bumpy/Flare 2-3 shifts
- Slipping gears

Note: Requires tool kit F-68942-TL27 & the VB-FIX reaming fixture.

10 68942-31K
**3-4 Overlap
Control Valve Kit**



Helps cure:

- Harsh/Bumpy/Flare 3-4 shifts
- Slipping gears

Note: Requires tool kit F-68942-TL31 & the VB-FIX reaming fixture.

11 68942-05K
**Overlap Control Valve
Sleeve Kit**

This kit fits 3 locations!
(Parts also sold separately)

Helps cure:

- Harsh/Bumpy/Flare shifts
- Slipping gears

12 68942-01
**Solenoid Pressure
Regulator Spring**

'99-Earlier Units

Helps cure:

- Delayed engagements
- Flare 2-3, 3-4 or 4-5 shifts

