

Accumulator Piston Kit

Part No.

22841-04K


- 1 Accumulator Piston
- 2 Teflon® Seals
- 2 D-ring Seals

Part No.

22841-04SK

Replacement Seal Kit

CHRYSLER 727, 904, 42-46-47-48RH/RE



Instructions:

Installation

1. Remove OEM piston and discard
2. Clean and inspect the bore
3. Install Teflon® and D-rings per illustration

Reassembly

1. Lubricate seals
2. Install