


TCC Boost Valve Kit

119940-01K

1 TCC Boost Valve & Sleeve
1 TCC Spring



Instructions:

1. If significant wear/leakage is noticed, replace the worn OEM valve and sleeve with the new Sonnax kit.
2. The TCC spring provided in this kit is a direct replacement spring in case the OEM spring is broken or fatigued.

Wear Test:

The aluminum sleeve is often visibly worn. Bellow are instructions for a WAT (Wet Air Test) procedure to determine wear:

