



Clutch Release Kit

Part No.

MB-CP-10K


- Steel Clutch Plate with Spring Notches
- Clutch Release Spring (10)

Also Available


- **MB-CP-10R** Steel Clutch Plate with Spring Notches
- **MB-S-1** Clutch Release Spring (100/bag)

Illustration Reference

MB-CP-10K is item number 16 as shown below. For detailed illustration, visit www.sonnax.com.



Mercedes 722.6



Sonnax clutch release kit **MB-CP-10K** is designed to address the common complaint of poor torque converter clutch performance in Mercedes 722.6 units. The most noticeable problem is cold engine stall on engagement, with other complaints such as shudder, engine lugging and clutch wear also possible.

For more information, visit the Torque Converter section of the Sonnax online Technical Library at www.sonnax.com and select *Mercedes 722.6: Cold Stall/TCC Shudder, Part 1 & 2*.

Features & Benefits

- Improved clutch performance
- Eliminates cold engine stall on engagement
- Eliminates coast down shudder
- Reduces clutch wear